PROTECTION FRAMEWORK

EN 420: 2003+A1: 2009 – General requirements for protective gloves related to ergonomics, manufacture, resistance to materials, harmlessness, comfort, effectiveness, and marking.

EN 388: 2016 – Glove standard related to protection against mechanical risks (abrasion, blade cut resistance, tear resistance & puncture resistance), and if neccessary against impact.

For professional use: **Fishing - agriculture - food industry – cleaning**, or other activities requiring this kind of protection in environments representing an average risk of blade cuts.

THIS ARTICLE IS A

CATEGORY 2 PPE

And complies with EU regulation 2016/425

PPE = Personal Protective Equipment

PERFORMANCE

EN 420: 2003+A1: 2009

Dexterity = Level 4 (6.5 mm pin diameter picked up with a gloved hand 3 times in 30 seconds)

EN 388: 2016



a.Abrasion resistance = Level 4 (≥ 8000 cycles)
b.Circular blade cut resistance = Level 1 (index between 1.2 et 2.5)
c.Tear resistance = Level 2 (≥ 25 Newtons)
d.Puncture resistance = Level 1 (between 20 and 60 Newtons)

ILLUSTRATION AND INSTRUCTIONS



PRINCIPAL MATERIALS

PVC
Cotton

For maximum protection, check the condition of your gloves thoroughly before use.

DO NOT USE gloves that are soiled, damaged or have holes in them.

INSTRUCTIONS

- CARE

- Gloves should not remain soiled.
- Wash with a mild liquid detergent.
- Rinse well in fresh water.
- Dry them properly in a well-ventilated place.

- STORAGE

- Keep the gloves in a dry place, away from light.

Colour: blue

Sizes: M – L – XL – XXL

8 – 9 – 10 – 11 (according to EN 420: 2003+A1: 2009)

The lifespan of the gloves is linked to conditions of use and quality of care